

---

# Contents

<b>1</b>	<b>Introduction</b>	<b>1</b>
1.1	The Exactness of Science	2
1.2	Data Without Uncertainty	4
<b>2</b>	<b>Basics on Data</b>	<b>7</b>
2.1	What Is a Measurement?	8
2.2	Analog vs. Digital	11
2.3	Dealing With Data (Numerals)	12
<b>3</b>	<b>Basics on Uncertainties (Errors)</b>	<b>15</b>
3.1	Typical Sources of Internal Uncertainties	16
3.2	Definitions	17
3.3	Uncertainty of Data Depending on One Variable	26
3.4	Multiple Uncertainty Components (Quadratic Sum)	27
<b>4</b>	<b>Radioactive Decay, a Model for Random Events</b>	<b>33</b>
4.1	Time Interval Distribution of Radioactive Events	33
4.2	Inductive Approach to Uncertainty (Example)	39
<b>5</b>	<b>Frequency and Probability Distributions</b>	<b>51</b>
5.1	Frequency Distribution (Spectrum)	51
5.2	Probability Distributions	58
5.3	Statistical Confidence	65
5.4	Dealing with Probabilities	66
<b>6</b>	<b>Deductive Approach to Uncertainty</b>	<b>71</b>
6.1	Theoretical Situation	71
6.2	Practical Situation	71
6.3	Regression Analysis (Least-Squares Method)	81
6.4	Data Consistency Within Data Sets	87

<b>7</b>	<b>Correlation</b> .....	91
7.1	Introduction .....	91
7.2	Correlated (Systematic) Internal Uncertainties .....	93
7.3	Differentiation From "Systematic Errors" .....	104
7.4	Correlation in Cases of Linear Regression .....	108
7.5	Data Consistency Among Data Sets .....	113
7.6	Target Shooting as a Model for Uncertainties .....	118
<b>8</b>	<b>Dealing With Internal Uncertainties</b> .....	121
8.1	Calculations With Both Types of Uncertainties .....	124
8.2	Total Uncertainty .....	132
8.3	Using Internal Uncertainties for Diagnosis .....	135
<b>9</b>	<b>Presentation and Estimation of Uncertainties</b> .....	141
9.1	Graphic Presentation, Also of Uncertainties .....	141
9.2	Correct Presentation of Uncertainties .....	145
9.3	Finding the Size of Internal Uncertainties .....	146
9.4	Estimating the Size of (Internal) Uncertainties .....	148
<b>10</b>	<b>Feedback of Uncertainties on Experiment Design</b> .....	153
10.1	Optimizing Experiments .....	153
10.2	Optimizing Background Measurements .....	155
10.3	Optimizing With Respect to Dead Time .....	158
10.4	Optimizing in View of the Mathematical Presentation .....	160
10.5	Achieving the Smallest Overall Uncertainty .....	162
<b>Solutions</b> .....		171
<b>Index</b> .....		179